


TYPICAL RESPONSE CURVES FOR BOLT SWITCH TYPE GFR & LGFR RELAYS

Cardinal points are shown for clarity only. The actual time delay adjustment is continuously variable between instantaneous and 0.9 second. The time delay tolerance is $\pm 10\%$ at full scale and $\pm 20\%$ of indication at other settings.



NOTES:

1. Relay may trip @ 100% of trip threshold.
2. Relay must trip @ 115% of trip threshold.
3. For a special calibration certificate, please consult the factory.